

**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Landbridge – Station S1**



**Area H – Station S2**



**Appendix A – Slope Stability and Erosion Areas**  
**Tourtelot Annual Inspection Report**  
**April 2009**

**Area C – Station S3**



**Area A – Station S4**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Area A – Station S5**



**Area A – Station S6**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Area A – Station S7**



**Area A – Station S8**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Area F/G – Station S9**



**Area G – Station S10**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Area G – Station S11**



**Area G – Station S12**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Area G – Station S13 (Direction of Photo Arrow Match)**



**Area G – Station 13 (Direction of Original Photo Match)**




**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Area B – Station S15**



**Area I – Station S16**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Area H – Station S18**




**Area J – Station S20**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2009**

**Slump in Area H Unchanged from the 2007 and 2008 Inspection**



**Line of slump found in 2007, no change change detected.**