

**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Landbridge – Station S1**



**Area H – Station S2**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Area C – Station S3**



**Area A – Station S4**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Area A – Station S5**



**Area A – Station S6**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Area A – Station S7**



**Location of new slide identified  
Area A – Station S8**



**A new slide has been identified in this area. See photos at the end of this Appendix.**

**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Area F/G – Station S9**



**Area G – Station S10**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Area G – Station S11**



**Area G – Station S12**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Area G – Station S13 (Direction of Photo Arrow Match)**



**Area G – Station 13 (Direction of Original Photo Match)**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Area B – Station S15**



**New Slump in 2011– See additional photos | Slump from 2010**

**Area I – Station S16 | Photo access limited by water height. Station is under water**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Area H – Station S18**



**Area J – Station S20**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**Slump in Area B**



**New Slump as noted in Area B – Station 15 photo**

**Appendix A – Slope Stability and Erosion Areas  
Tortelot Annual Inspection Report  
April 2011**

**Another view of the slump in Area B. This slump is located above Sewer Road and is a new slump which lies above the slump identified below Sewer Road in this area in 2010.**



**Appendix A – Slope Stability and Erosion Areas  
Tourtelot Annual Inspection Report  
April 2011**

**New Slump found in Area A at Station S7 during the 2011 inspection**



**Another view of the new slump in Area A.**

