

**Appendix C – Land Bridge Mesh Barrier
Tourtelot Annual Inspection Report
April 2011**

McAllister Drive



**Appendix C – Land Bridge Mesh Barrier
Tourtelot Annual Inspection Report
April 2011**

**McAllister Drive
Mesh Barrier shows good contact with the surface**



Top of Slope along the east side of McAllister Dr.



**Appendix C – Land Bridge Mesh Barrier
Tourtlot Annual Inspection Report
April 2011**

A small section lifted from the slope at the on the west side of McAllister Drive.



**Appendix C – Land Bridge Mesh Barrier
Tourtlot Annual Inspection Report
April 2011**

**Mesh Barrier on the eastern slope of McAllister Dr.
Barrier is intact and has good contact with the slope.**



**Appendix C – Land Bridge Mesh Barrier
Tourtelot Annual Inspection Report
April 2011**

**Additional Photo of Mesh Barrier
Anchoring pin lifting from the surface along the top of slope on the west side of
McAllister Dr.**

