

Appendix A – Slope Stability and Erosion Areas
Tourtlot Annual Inspection Report
June 2014

Landbridge – Station S1



Area H – Station S2



3

**Appendix A – Slope Stability and Erosion Areas
Tourtelot Annual Inspection Report
June 2014**

Area C – Station S3



Area A – Station S4



Appendix A – Slope Stability and Erosion Areas
Tourtelot Annual Inspection Report
June 2014

Area A – Station S5



Area A – Station S6



**Appendix A – Slope Stability and Erosion Areas
Tourtelot Annual Inspection Report
June 2014**

Area A – Station S7



Area A – Station S8



Appendix A – Slope Stability and Erosion Areas
Tourtlot Annual Inspection Report
June 2014

Area F/G – Station S9



Area G – Station S10



**Appendix A – Slope Stability and Erosion Areas
Tourtelot Annual Inspection Report
June 2014**

Area G – Station S11



Area G – Station S12



**Appendix A – Slope Stability and Erosion Areas
Tourtelot Annual Inspection Report
June 2014**

Area G – Station S13 (Direction of Photo Arrow Match)



Area G – Station 13 (Direction of Original Photo Match)



Appendix A – Slope Stability and Erosion Areas
Tourtlot Annual Inspection Report
June 2014

Area B – Station S15



Area I – Station S16



Appendix A – Slope Stability and Erosion Areas
Tourtlot Annual Inspection Report
June 2014

Area H – Station S18



Area J – Station S20

