Appendix A – Slope Stability and Erosion Areas
Tourtelot Annual Inspection Report
April 2010

Landbridge – Station S1

Area H – Station S2

Area C – Station S3

Area A – Station S4

Area A – Station S5

Area A – Station S6

Area A – Station S7

Area A – Station S8

Area F/G – Station S9

Area G – Station S10

Area G – Station S11

Area G – Station S12

Area G – Station S13 (Direction of Photo Arrow Match)

Area G – Station 13 (Direction of Original Photo Match)

Area B – Station S15

New Slump – See additional photos

Area I – Station S16

Area H – Station S18

Area J – Station S20

Slump in Area H Unchanged from the 2007 and 2008 Inspection

Line of slump found in 2007, no change change detected.

New Slump found in Area B during the 2010 inspection



This slump measured 4' in width and 12' in total length. This is in a Historic Landslide Area. Monitoring will continue.

Another view of the slump in Area B

Historic Slide Area A is to the right and the new slump is in Area B