Appendix C – Land Bridge Mesh Barrier
Toutelot Annual Inspection Report
April 2010

McAllister Drive

Condition of Mesh Barrier at the Top of Slope on the west side of McAllister Drive.

Wire Mesh Barrier lifting from the slope

Additional Photos of Mesh Barrier