

Appendix B: Master List

Appendix B

Master List

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
W	174	Booster Pump House (Firewater)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	176	Sewage Pump House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	177	Compressor Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	194	Septic Tank	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended at this site to determine the potential groundwater impacts from the possible discharge into the septic tank from the former NIKE missile repair and support facilities (CL1).
	195	Septic Tank	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C419	Large-Size Igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C420	Large-Size Igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	CL1	Clip-link and belt plant (1942-1944); guided missile shop/NIKE missile repair & rebuilding	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Site requires further investigation for possible releases of solvents from waste discharged from CL1.
	CL2	Boiler House	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional research is recommended to determine the status of the UST.
	CL3	Change Room	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	CL4	Paint Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D501	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D502	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D503	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D504	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D505	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D506	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D507	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D508	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D509	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D510	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D511	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D512	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D513	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D514	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D515	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D516	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D517	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D518	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D519	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D520	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D521	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
W	D522	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D523	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D524	Small Arms Magazine Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D525	Small Magazines Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D526	Small Magazines Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D527	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D528	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	D529	Igloo Magazines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	DL2	Dunnage Equipment Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	M2	Firehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	M3	Storage (unspecified)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	M4	Equipment Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	M8	Tool Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	M11	Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS35	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS36	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS37	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS38	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS39	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS50	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	PL4	Loading Platform	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	PL5	Loading Platform	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	R5	Reservoir (firewater)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Rail yard	Overland Shipment of Ordnance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	SA1	Small Arms Ammunition Storage Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	SA2	Small Arms Ammunition Storage Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Tank Test Track/Shop	Mechanical Performance Tests	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	TO59	Barracks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	TS1	By end of 1956, transitory shelter/warehouses for NIKE missiles. In 1962, identified as Barracks.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	TS2	By end of 1956, transitory shelter/warehouses for NIKE missiles. In 1962, identified as Barracks.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
W	TS3	Transitory Shelter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	TS4	Transitory Shelter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W1	Inert Materiel Warehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W2	Inert Materiel Warehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W3	Inert Materiel Warehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W4	Inert Materiel Warehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W6	Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W9	Warehouse/Storage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional research is recommended to determine the status of these USTs.
	W10	Warehouse/Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W11	Warehouse/Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W12	Warehouse/Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
		Waste Areas/Open Ditch	Waste Areas/Open Ditch	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
I	4	Sandblast Building/Paint Spray	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended at this site to determine the potential groundwater impacts from the possible disposal of solvent-based and lead-based paints downgradient of the building.
	15	Pump house-fuel oil	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	The above ground portion of the fuel lines at Building 15 (confirmed by the geophysical survey) was recommended to be removed as a preventative measure to eliminate the potential for future use. The below ground portion of the fuel lines was recommended to be abandoned in place. Based on these recommendations, this site requires further action to complete these tasks.
	22	Transformer House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	23	Transformer Vault	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	25	Lieutenant's quarters	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Based on the findings from this investigation, no further investigation is recommended.
	26	Lieutenant's quarters	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Sub-meter GPS information is required for all such cases for inclusion in the RWQCB's regional leaking UST database and the statewide Geotracker database.
	27	Captain's Quarters	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Investigation into the location of the suspected UST is recommended. If the UST is located, a subsurface investigation is recommended to determine the presence or absence of fuel, oil, and lead in soil and groundwater (if present) for a possible release from the UST.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
I	28	Quarter's Commanding Officer	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Sub-meter GPS information is required for all such cases for inclusion in the RWQCB's regional leaking UST database and the statewide Geotracker database.
	29	Storehouse for guns, explosives, paints, oils, gunpowder, and various types of weaponry.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	30	Water Pump house	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	31	Store House/Engine Rebuild	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuel and oil in groundwater downgradient of the site for a potential release from former cleaning and degreasing activities. Additional research is also recommended to determine the status of the suspected UST.
	41	Pump House-Sewage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	42	Garage/Repair Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuel, oil, and solvents in groundwater downgradient of the site for a potential release from former cleaning and degreasing activities.
	44	Utilities building/Mechanical Shop/Electrical Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	45	Enlisted Men's Barracks	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Investigation into the location of the suspected UST is recommended. If the UST is found, a subsurface investigation is recommended to determine the presence or absence of fuel, oil, and metals in soil and groundwater (if present) from a possible release from the UST.
	46A	Vocational Training Paint and Carpenter Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	46(B)	Office Building	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Investigation into the location of the suspected UST is recommended. If UST is present, conduct a subsurface investigation is recommended to determine the presence or absence of fuel, oil, and metals in soil and groundwater (if present) from a possible release from the UST.
	47	Storehouse/Office building	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional research is recommended to determine the location of the fuel tank. Based on this research, a geophysical survey should be conducted to confirm the location of the tank and then a subsurface investigation to determine the presence or absence of fuel, oil, and metals in soil and groundwater from a possible release from the suspected fuel tank.
	48	Shop/Storage C&P	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

Appendix B

Master List

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
I	49	Machine Shop/Fire Control and Optical Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	51	Stable/Maintenance	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuels, semi-volatiles, metals and oil in soil and fuels, oils and solvents in groundwater (if present) from a possible release from this former drum storage area and former maintenance activities.
	52	Storehouse/Office/Photographic Laboratory	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	53	Dynamometer Shop/Engine Testing/Fuel storage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	The RWQCB requested further delineation of fuels and lead in soil and groundwater based on the fuels and associated analytes reported in soil and groundwater from a release from the former UST.
	54	Pump House-Water/Store House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No investigation is recommended for the possible explosives.
	55	Blacksmith Shop/Machine/Welding Shops	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is required at this site based on the 1999 investigation. Additional sampling is recommended to determine the lateral extent of fuels and solvents in groundwater downgradient of this building (and complex).
	55A	Welding Shop/Machine Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	56	Leather & Canvas Shop/Welding Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the lateral extent of fuels and solvents in groundwater downgradient of the building (and complex).
	56A	Small Arms Shop/Leather Canvas Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the lateral extent of fuels and solvents in groundwater downgradient of the building (and complex).
	56B	Welding Shop and possible foundry	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No further action under FUDS is recommended for this building.
	56C	Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	57	Small Arms Shop, Firing Range	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the lateral extent of fuels and solvents in groundwater downgradient of the building (and complex).
	57A	Small Arms Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No further DoD action is indicated (NDAI) for this site.
	57B	Small Arms Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	57C	Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
I	58(A)	Small Arms Repair and Retinning/Boiler Room	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Recommendations were made to conduct an additional soil assessment to determine the lateral and vertical extent of TPH, lead, and PAHs at former Building 58(A) (ref 1207). Additionally, an investigation is recommended to further delineate the presence of fuels and solvents in groundwater downgradient from this former building (and existing complex).
	58(B)	Transformer House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	59	Tool House/Degreaser Pit	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Investigation is recommended to determine the presence or absence of fuels, solvents, metals and oils in groundwater downgradient of the building for a potential release from degreasing activities.
	59(A)	Tool House	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	The report recommends conducting an additional soil investigation to determine the lateral and vertical extent of TPH and PAHs for the suspected USTs beneath the southeast corner of Building 56A and the tool house at former Building 59(A). (ref 1207). Additionally, an investigation is recommended to further delineate the presence of fuels and solvents in groundwater downgradient of this building (and complex).
	60(B)	Storehouse Group K-Chemical Stores	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	62	Surveillance Laboratory	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	63	Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	64	Pump House	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional research is recommended to determine if this building and associated tanks/pumps were used beneficially.
	65(A)	Boiler House	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Recommendations were made to conduct an additional soil assessment to determine the lateral and vertical extent of TPH, lead, and PAHs at former Building 65(A). Additionally, an investigation is recommended to further delineate the presence of fuels and solvents in groundwater downgradient of the former building (and complex).
	65(B)	Boiler House	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Recommendations were made to conduct an additional soil investigation or site-specific risk analysis to determine the extent or risk of lead at the former machine gun test firing range at Building 65(B) and for the soil removed from the former boiler house. (ref 1207).
	66(A)	Paint Shed/Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No further action under FUDS recommended for this site (ref 1207).

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
I	66(B)	Paint Shed/Paint Shop/Welding Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	68	Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	69	Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	70	Powerhouse for entire Arsenal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	71	Artillery and Ordnance Material Storehouse	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of the UST through geophysical and/or subsurface investigation downgradient of the suspected location for a possible release.
	72	Hospital/Infirmary	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of the fuel tank and/or subsurface investigation downgradient of the suspected location.
	73(A)	Service Station and Scales	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No further action under FUDS is recommended for the reported UST (ref 1077). The source of the groundwater contamination is not Building 73(A), but should be determined.
	73(B)	Storehouse, Spec. Inert Materials	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	74	Photography laboratory (Former Bakery)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Post-Army use occurred until at least 1973. These uses, which included candy manufacturing and instrument repair, presumably benefited from the existing sewer system at Site 74. As noted in our response to Comment No. 2, sewage lines that have been in use since closure of the former Arsenal are considered to provide beneficial use to the current owners. Pursuant to Chapter 3, Section 7.2.3.5 of USACE Engineering Circular EC-200-3-7, DERP-FUDS Program Manual, dated 30 September 1999, beneficially used facilities are ineligible for investigation under the FUDS Program.
	88	Storehouse	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Site visit and interview with property owner is recommended to determine the presence of the AST.
	89	Storehouse	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Site visit and interview with property owner is recommended to determine the presence of the AST.
	89A	Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	90	Locomotive Building	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, solvents, and oils in groundwater downgradient of the building for a potential release from possible cleaning and degreasing activities in the building.

Appendix B

Master List

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
I	91	Machine Shop/Combat Vehicle and Artillery Repair	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, solvents, and oils in groundwater downgradient of the building for a potential release from former cleaning and degreasing activities.
	91A	Temporary Machine Shop/Engine Rebuild	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, solvents, and oils in groundwater downgradient of the building for a potential release from former cleaning and degreasing activities.
	92	Headquarters/office building/Photographic Laboratory	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	USACE's position is that any building, structure or system that remained in use after the Army left the former Arsenal has the possibility of use. These structures are ineligible for investigation under the FUDS program. Therefore, no DoD action is indicated (NDAI) for this site.
	93	Truck Storage Building/MMW Repair, Motor Vehicle Maintenance Building.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, solvents, and oils in groundwater downgradient of the building for a potential release from former vehicle maintenance activities.
	95	Wharf	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for the Wharf.
	97(A)	Transformer house on wharf	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	98	Carpenter Shop/Machine Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	99	Storehouse/Shop Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	99A	Storehouse/Shop Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	101	Battery Charge Building	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Site requires investigation in regards to the former DoD activities with the steam cleaning of the battery cases. Downgradient water sampling is proposed to determine the possible impacts of metals dissolved in groundwater with sampling focused along the sewer line where the waste was carried.
	103	Service station/office building	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	In response to the RWQCB request on the March 2002 investigation results, the site requires further investigation to determine the lateral extent of fuels in soil and groundwater for a release from the former UST.
	105	Fire station and fire training site	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No further DoD action is indicated (NDAI) for this site.
	108	Hoist building on wharf	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for the Wharf and associated buildings on it.
	114	Oil Storage Shed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	116	Carpenter Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

Appendix B

Master List

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
I	117	Sticker Building/ Carpenter Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	118(A)	Diesel tank, Fuel Oil Tank, Oil Storage Tank	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Further investigation is recommended to determine the lateral extent of fuels in soil and groundwater for a possible release from the former ASTs and solvents in groundwater from an unknown upgradient source.
	118(B)	Incinerator-sawdust disposal system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	119	Incinerator/Sawdust Disposal System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	120	Quartermaster Storage/Shop/Electroplat ing	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Investigation is recommended to determine the lateral extent of fuels in groundwater from a potential release from the former USTs beneath the building and solvents in groundwater for a potential release from degreasing activities in the former electroplating shop.
	142	Steam Cleaning Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	152	Building is a 21,000- gallon fuel tank	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No further action under the FUDS program was recommended for Building 152 because TPH was below regulatory limits and the AST has been removed.
	154	Motor Test Shed/Paint Spray/ Fuel storage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	The extent of TPH in groundwater was not defined and the RWQCB agreed in further investigation for fuels and lead for a release from the former USTs (ref 1079).
	156	Locomotive House	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuels, oils, and solvents in groundwater downgradient of Building 156 for a potential release from cleaning or maintenance activities at the former locomotive building.
	157	Lumber Shed/Storage Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	161	Motor Cleaning Building/Steam Cleaning/Paint Spray/Fuel Storage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A geophysical investigation is recommended to determine if the UST still exists. A subsurface investigation is recommended to determine the presence or absence of fuels, oils and solvents in groundwater downgradient from Building 161 for a potential release from the UST or cleaning activities in the former motor cleaning building.
	163	Warehouse and Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	165	Reclamation Building/Transport Vehicle Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuels, oils, and solvents in groundwater downgradient from Building 165 for a potential release from former cleaning activities.

Appendix B

Master List

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
I	165A	Steam Cleaning Building	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuels, oils, and solvents in groundwater downgradient of this site for a potential release from former cleaning activities.
	166	Paint Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuels, oils, and solvents in groundwater downgradient from this site for a potential release from former cleaning activities in the building.
	167	Bar Stock Building/Storage/Vehicle Shop for original Motor Pool	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Since these buildings are located within a known area of industrial activities that included maintenance, a subsurface investigation is recommended for a potential release from possible maintenance activities.
	168	Bar Stock Building/Storage/Vehicle Shop for original Motor Pool	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Since these buildings are located within a known area of industrial activities that included maintenance, a subsurface investigation is recommended for a potential release from possible maintenance activities.
	169	Rigger's building storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	178	A series of ASTs on a bluff overlooking Buildings 90 and 156.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	A site investigation report recommended no further action under the FUDS program for Building 178 (ref 1063).
	179	Compressor Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	180	Transformer building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Fillsite 1 (Formerly Landfill 1)	Dump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Site requires further investigation to determine the lateral extent of fuels and solvents in groundwater from an unknown source area.
	Fillsite 2 (Formerly Landfill 2)	Fillsite	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	USACE has not had control over the fillsite. USACE tried to sample groundwater downgradient of the fillsite, but there was no groundwater. Therefore, there is no risk to human health or the environment and no DoD action is indicated (NDAI) for this site.
	NIKE Missile Site 3	Defense	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Since the site never existed, no DoD action is indicated (NDAI) for this site.
	OS1	Lumber Storage and Receiving Shipments. Storage of Ordnance and General Supplies.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS2	Lumber storage and storage of ordnance and general supplies	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS3	Open storage of ordnance and general supplies. Potentially used for lumber storage.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
I	OS5	Open storage of ordnance and general supplies	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS12	Open storage of ordnance and general supplies	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Quarry 3	Sandstone Quarry	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No further action under FUDS is recommended.
	Service Station west of Building 45	Civilian Service Station	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Based on the limited information no DoD action is indicated (NDAI) for this site.
	Sewer/Storm Drainage System	Sewer, storm drain	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Smoke Stack	Smoke Stack/Incinerator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No further action under FUDS was recommended (ref 1207).
	T116	Carpenter Shed Addition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	T-138	Wharf Shed/Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	T-139	Wharf Shed/Storage on Wharf 95	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	T-141	Wharf Shed/Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	T-143	Wharf Shed/Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	T197	Box Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	T199	Maintenance Building, Body and Radiator Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, solvents and oils in groundwater downgradient of the building for a potential release from former maintenance activities.
	TO127	Storehouse/Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
TO131	Storehouse/Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended for this building to determine the presence or absence of solvents in groundwater downgradient of the building for a potential release from former cleaning and degreasing activities.	
TO132	Storage - salvage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.	
R	Artillery Testing Area	Artillery Testing Area	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Drainage Channels	Drainage Channels	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Farm Structures (1), (2) and (3)	Farm Structures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS51	Open Storage Area	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Overturned Truck Area	Overturned Truck Area	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Present Day Police Firing Range	None Identified	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

Appendix B

Master List

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
R	Small Arms Ammunition Disposal Burn Cage	Small Arms Ammunition Disposal Burn Cages	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Spur A	Revetment and Burn Cage Area/Hydrazine Burn Area (1958/59)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	The exact location of the burn cage is not known. Kerosene and the "residues" from the burning are possible chemicals of concern. Nitrosamines are also possible chemicals of concern but not likely present. Therefore, it is recommended that Spur E, a known location of a burn cage is investigated. If impacts are found, then a subsurface investigation is recommended at Spur A.
	Spur B	Revetment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Spur C	Revetment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Spur D	Revetment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Spur E	Revetment and Burn Cage Area	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Because this site is a known location of a burn cage, a subsurface investigation is recommended to determine the presence or absence of fuels, metals, and explosives in groundwater downgradient for a potential release from the fuels used to burn the ammunition and disposal of residues left-over from the burning of the ammunition.
	Spur F	Revetment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Spur G	Revetment and Burn Cage Area	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	The exact location of the burn cage is not known. Kerosene and the "residues" from the burning are possible chemicals of concern. Nitrosamines are also possible chemicals of concern but not likely present. Therefore, it is recommended that Spur E, a known location of a burn cage is investigated. If impacts are found, then a subsurface investigation is recommended at Spur G.
	T500	Tool Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Water Supply Wells and Pump House	Unknown	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
M	1	Hospital	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	2	Powder Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	3	Powder Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	5	Photographers Shop	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	7	Ordinance, Storehouse, Indoor Firing Range	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	8	Ammunition Shop/Radio Mars	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
M	9	Ordnance Storehouse, Ammo Shop and Utilities Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	10	Powder Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	12	Powder Magazine, Chemical Warfare Material Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	13	Powder Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Therefore, no DoD action is indicated (NDAI) for this site.
	14	Powder magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Therefore, no DoD action is indicated (NDAI) for this site.
	15(B)	High-Explosives Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	16(A)	Ammunition Renovation Plant	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	16(B)	Pump House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	17	Booster Pump House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	19	Pump House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	20	Boiler House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	50	Paint Shop/Equipment Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional research is recommended to determine if the tanks removed in 1987 are associated with 500-gallon stove oil or 5,500 gallon road oil tanks.
	75	Type 32 Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	76	Type 32 Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	77	Underground Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	78	Underground Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	79	Underground Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	80	Underground Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	81	Type 34 Magazine/Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	82	Type 34 Magazine/Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	83	Type 34 Magazine/Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	84	Type 34 Magazine/Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	85	Type 34 Magazine/Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
M	86	Underground Magazine	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	96	Shell Loading Office	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	97(B)	Shell Loading Office	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	109	Deboostering Barricade	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	111	Heavy Equipment Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuel, oils, and solvents in groundwater downgradient of the site for a potential release from cleaning activities at the heavy equipment yard.
	112	Booster Pump House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	136	Heavy Equipment Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	146	Surveillance Shelter, Railroad Dispatch Office	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	147	Unknown	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	148	Heating Plant/Tool Shed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	155	Field Office/Tire Recapping after 1950	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	160	Boiler House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	170	Auto Parts/Office/Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	171	Vehicle Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuels, oils, and solvents in groundwater downgradient from this site for a potential release from former automotive maintenance and repair activities.
	172	Vehicle Repair and Maintenance Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A subsurface investigation is recommended to determine the presence or absence of fuels, oils, and solvents in groundwater downgradient from this site for a potential release from former automotive maintenance and repair activities.
	173	Office/Storehouse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	175	Gasoline Service Station	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	203 (at R1)	Water Chlorination	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	208 (at R1)	Filtration Plant	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Artesian well	Irrigation/Boiler Water/Other Non- Potable Uses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
Chemical Warfare Disposal	Chemical Warfare Disposal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.	

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
M	Concrete Lined Underground Tank	Suspected Water Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Drainage Canal	Tidewater and Flood Control/Domestic Waste Collection	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Dunnage Burn Area	Burning of Scrap Wood	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Fillsite 3 (formerly the Dumpsite)	Dumpsite	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, solvents, and oils in groundwater downgradient of the site for a possible release from waste discharged at this site.
	Ordnance Disposal Site	Ordnance Disposal Site	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	OS14	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS15	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS16	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS17	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS20	Open Storage, Maintenance, Civilian Parking	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS21	Open Storage, Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS24	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS25	Open Storage - Ordnance Disposal Site	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS25A	Storage of NIKE Test Equipment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS27	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS28	Open Storage, Vehicle and Equipment Storage and Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS29	Open Storage of Drums Containing Industrial Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS30	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS31	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS46(A)	Open Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
Popping pot (formerly the Incinerator)	Incineration	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, explosives, metals and oils in groundwater downgradient of the site for a possible release from waste disposed of from the popping pot.	
Post Dumpsite (formerly Landfill 3)	Dumpsite	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Because there is evidence that the area received discharge of liquid metal cleaning corrosives, USACE proposes to investigate this site.	

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
M	Primer Destruction Area M	Primer Destruction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	Quarry 1	Building Material/landfill	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Based on the results from this trenching and sampling activities, no further DoD action is indicated (NDAI) for this site.
	Quarry 2	Primer Destruction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	There are no HTRW related issues for this site and therefore no DoD action is recommended.
	R1	Fire-Fighting Water Reservoir	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	R2	Potable Water Reservoir	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	R3	Fire-fighting Water Reservoir	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	R4	Fire-fighting Water Reservoir (Pine Lake)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Salvage yard	Salvage Yard	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuel and oil in groundwater for a potential release from former disposal activities.
	Small Arms Range	Small Arms Range	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	T221	Garage Vehicle Maintenance	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, solvents, metals and oils in groundwater downgradient of the building for a potential release from former maintenance activities.
	T222	Steam Cleaning	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of fuels, solvents, and oils in groundwater downgradient of the former building for a potential release from former cleaning activities.
	T226	Office	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	TO68	Laundry/Barracks for Prisoners of War	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	TO73	Recreation and Storage Building/Photo Lab/Depot Facilities Shop	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Additional investigation is recommended to determine the presence or absence of solvents in groundwater downgradient of the building for a potential release from former cleaning activities.
	W7	Salvage Warehouse/General Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	W8	Gas Cylinder Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Waste Water Discharge	Waste Water Discharge	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	In accordance with the FUDS program, the sewer/storm drain system is no longer the responsibility of DoD since the system was used after the Army left. Therefore, no DoD action is indicated (NDAI) for this site.
	Well 1	Water Well	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
M	Well 2	Water Well	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
S	110	Railroad Tool House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A201	Large-Size Igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A202	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A203	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A204	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A205	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A206	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A207	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A208	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A209	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A210	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A211	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A212	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A213	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A214	Large-size igloos; Storage of radio nuclides	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A215	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A216	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A217	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A218	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A219	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A220	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A221	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A222	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A223	Medium-size igloos; Storage of smokeless powder	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A224	Medium-size igloos; Storage of blasting equipment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A225	Large-size igloos; Storage of TNT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A226	Medium-size igloos; Storage of explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A227	Medium-size igloos; Storage of explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A228	Medium-size igloos; Storage of explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A229	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A230	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
S	A231	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A232	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A233	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A234	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A235	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A236	Large-size igloos; Storage of ammunition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	A237	Large-size igloos; Storage of missiles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B301	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B302	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B303	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B304	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B305	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B306	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B307	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B308	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B309	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B310	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B311	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B312	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B313	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	B314	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C401	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C402	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C403	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C404	Medium-size igloos; Storage of rubber	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C405	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C406	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C407	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C408	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C409	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C410	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C411	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C415	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C416	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C417	Large-size igloos; Inspection of ammunition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.

**Appendix B
Master List**

Area	DoD Facility ID	DoD Uses	NDAI	FAR	IRR	Recommendations
S	C421	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C422	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C423	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C424	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C425	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C426	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C427	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C428	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C429	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C430	Medium-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C431	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C432	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	C433	Large-size igloos	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	DL1	Dunnage Equipment Building	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Elliptical formation	Unknown	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	Firing range	Demolition of Ammunition/ Test Firing of .45 and .50 Caliber Weapons	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Soil sampling is recommended to determine the presence or absence of metals in soil at the target butt.
	M9	Railroad Tool House	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	NIKE Missile Site 1	Defense	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	NIKE Missile Site 2	Defense	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS34	Vehicle, Weapons Storage and Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	OS46(B)	Vehicle, Weapons, Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	PL1	Loading Platform	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
	PL2	Loading Platform	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.
PL3	Loading Platform	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.	
Tank Test Track and Repair Shop	Off-road testing and adjustment of armored vehicles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
W5	Unknown	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	No DoD action is indicated (NDAI) for this site.	