Appendix A Slope Stability and Erosion Areas

Land Bridge – Station S1 May 2, 2006

Area H - Station S2 May 2, 2006

Area C – Station S3 May 15, 2006

Area A – Station S4 May 2, 2006

Area A – Station S5 May 2, 2006

Area A – Station S6 May 2, 2006

Area A – Station S7 May 9, 2006

Area A – Station S8 May 2, 2006

Area F/G – Station S9 May 2, 2006

Area G – Station S10 May 2, 2006

Area G – Station S11 May 2, 2006

Area G – Station S12 May 9, 2006

Area G – Station S13 May 9, 2006 (Direction of Photo Arrow Match)

Area G – Station 13 May 9, 2006 (Direction of Original Photo Match)

Slope Stability and Erosion Areas

Area B – Station S15 May 9, 2006

Slope Stability and Erosion Areas

Area I – Station S16 May 9, 2006

Area H – Station S18 May 9, 2006

Area J – Station S20 May 4, 2006

Slump in Area B, Above S-3 (Found during 2005 Survey) **May 9, 2006**

Erosion Area A, Above S-16 (Found in 2005 Survey) May 9, 2006

Slope Stability and Erosion Areas

New Slump Above and East of S-3

New Slide Above S—7 May 2, 2006

Slope Stability and Erosion Areas

New Slide Above S-18 May 2, 2006

Slope Stability and Erosion Areas

New Erosion Above S-16 in Groin of McAllister Land Bridge