

**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 1
374 Piercy Dr.**



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 2
372 Piercy Dr.**



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 3
380 Wool Ct.**




**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 4
478 Casey Ct.**



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 5
476 Casey Ct.**



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 6
477 Panarama Dr.**



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 7
603 Kearny St.**



Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009

Encroachment 8
605 Kearny St.



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 9
613 Kearny St. (This encroachment has remained unchanged since orginally
reported on in 2007)**



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

Encroachment 10

**699 Andrew Ct. (The concrete curb is a new encroachment for 2009, see item E in
“Encroachments Along Fence” from 2008 report – Andrew Court Rear Yards)**



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 11
438 Arguello Dr. (New encroachment for 2009)**




**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

**Encroachment 12
426 Arguello Dr. (New encroachment for 2009)**



**Appendix B - Encroachments Along Fence Line
Tourtelot Project Annual Inspection Report
April 2009**

Google Map of Encroachment Locations as recorded by Motion X GPS



**Appendix C – Land Bridge Mesh Barrier
Toutelot Annual Inspection Report
April 2009**

McAllister Drive (No change in 2009)



**Appendix C – Land Bridge Mesh Barrier
Toutelot Annual Inspection Report
April 2009**

Wire Mesh Barrier lifting from the slope

