

Primary #: \_\_\_\_\_  
 HRI # \_\_\_\_\_  
 Trinomial \_\_\_\_\_  
**NRHP Status Code:** \_\_\_\_\_  
 Other Listings \_\_\_\_\_  
 Review Code \_\_\_\_\_ Reviewer \_\_\_\_\_ Date \_\_\_\_\_

\*Resource Name or 333 East K Street

- P1. Other Identifier:
- \*P2. .Location: \*a. County Solano
- b. Address: 333 East K Street
- \*c. City: Benicia Zip 94510
- d. UTM: N/A
- e. USGS Quad: Benicia T2N R3W MDM
- \*f. Other Locational Data (APN #): 88-151-11

**\*P3a. Description**

This building is a good example of a Queen Anne cottage with a wrap around porch treatment. The house is L-shape in plan and is set on a slightly raised foundation. The principal roof is hip with a cross gable on the west side. The gable is trimmed with a fascia with eave returns and a plain verge board. The gable end is clad with fish scale shingles. The primary roof extends to cover the porch which is located on the east side of the front elevation and on the east side of the house. It has a spindle work frieze. The porch roof is supported with turned posts and the porch is enclosed with an open turned rail. The projecting wing on the west side of the front elevation has a ribbon of double hung windows occupying much of the wall surface. This is a prominent feature of the façade. Otherwise, fenestration consists of single double hung one-over-one windows. The house is clad with lap siding. The house has been meticulously rehabilitated.

**\*P3b. Resource Attributes:** HP2

**\*P4. Resources Present:**  Building  Structure  Object  Site  District  Element of District

**P5b. Description of Photo:**

Front façade, view north

**P5. Photograph or Drawing** (Photograph required for buildings, structures, and objects.)



**\*P6. Date Constructed/Age:**  
 Prehistoric  Historic  Both

**\*P7. Owner and Address:**  
 William Harsh  
 333 East K Street  
 Benicia, CA 94510

**\*P8. Recorded by:**  
 Carol Roland  
 Roland-Nawi Associates  
 4829 Crestwood Way  
 Sacramento, CA 95822

**\*P9. Date Recorded:** 9-25-05

**\*P10. Type of Survey:**  Intensive  
 Reconnaissance  Other

**Describe Eligibility Evaluation**

**\*P11. Report Citation:** none

**\*Attachments:**  NONE  Map Sheet  Continuation Sheet  Building, Structure, and Object Record  Linear Resource Record  Archaeological Record  District Record  Milling Station Record  Rock Art Record  Artifact Record  Photograph Record  Other (List):

## BUILDING, STRUCTURE, AND OBJECT RECORD

\*Resource Identifier: 333 East K Street

\*NRHP Status Code: 3D

B1. Historic Name: N/A

B2. Common Name:

B3. Original Use: Residence

B4. Present Use: Residence

\*B5. Architectural Style: Queen Anne

B7. Moved?  No  Yes  Unknown

Date: N/A Original Location: same

\*B8. Related Features: None

B9a. Architect: unknown

B9b. Builder: unknown

\*B10. Significance: Theme: Benicia Downtown District Period of Significance: 1847-1940

Property Type: Single Family Applicable Criteria: A / C

This residence is a good example of its style and type. It retains its important features including its gable treatment, fenestration, and porch with its frieze and tuned posts. The house retains its integrity of design, materials, workmanship, setting, location and association. It contributes to an East Side Historic District.

B11. Additional Resource Attributes: N/A

B12. References: McAlester, Virginia and Lee. *A Field Guide to American Houses*. New York: Alfred Knopf (1986); Bruegmann, Robert. *Benicia Portrait of an Early California Town: An Architectural History* (San Francisco: 101 Productions (1980); Woodbridge, Sally and Cannon Design Group. *Benicia, California: Downtown Historic Conservation Plan*. City of Benicia, 1990; Sanborn Map Benicia, CA. 1886; 1986 Benicia Historic Inventory form.


# BUILDING, STRUCTURE, AND OBJECT RECORD

Remarks: N/A

**B14. Evaluator:** Carol Roland, Ph.D.

Roland-Nawi Associates: Preservation Consultants  
4829 Crestwood Way  
Sacramento, CA 95822

**B 15. Date of Evaluation:** 9-25-05



(This space reserved for official comments.)