


City of Benicia
Accessibility Self Evaluation
Clock Tower

by Cathie Bigger-Smith, ARM, CSP, CPSI
January, 2013



1. Exterior Signage



2. Parking-Clock Tower



3. Front Entry



4. Interior front vestibule




5. Directional signage-interior front entry



6. Stairs to Assembly Area



7. Stair Interim Landing- no continuous rails



8. Lift signage



9. Gated entry to lift



10. Gripping handle-lift gate



11. Exterior lift gate



12. Lift operation power



13. Bottom level storage



14. Landing



15. Public phone booth/office area



16. Phone booth access



17. Exterior stairs-space between rails



18. Doors to kitchen



19. Kitchen prep/bar pass through



20. Gas range and hood



21. Dishwashing Area



22. Dance Area Extinguisher



23. Door encroaching into H/C access



24. Noncompliant H/C Stall



25. H/C stall access



26. Non accessible bar



27. Emergency Exit door to side of building



28. Bar service access