

ADA Report For Bus Stops

Location Name: Rose & Panorama

Standards Met:

1, 3, 5, 6a

Standards Not Met:

- 2 *Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
No bus stop pad only sidewalk
- 4 *Are all bus stop shelters/pads connected to the boarding area by an accessible*
No bus stop pad only sidewalk
- 6 *Are all bus route identification signs compliant with all sign requirements?*
Sign blocked by overgrown foliage. Difficult to see.

Location Name: Matthew Turner

Standards Met:

1, 5, 6a

Exceptions:

- 3 *Is the surface slope at all bus stops shelters, pads and egresses max 1:50 (2%)*
Surface slope of shelter is 12.4%. This is due to the slope of the hill --Exceptions Used (1, 3, 9, 10)

Standards Not Met:

- 2 *Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no bus stop pad only sidewalk
- 4 *Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no bus stop pad only sidewalk.

Location Name: Jack London

Standards Met:

3, 5, 6a

Standards Not Met:

- 1 *Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no shelter or pad. Room behind to construct.
- 2 *Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no shelter or pad. Room behind to construct.
- 4 *Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no shelter or pad. Room behind to construct.

Location Name: Rose Drive and Windsor

Standards Met:

3, 5, 6a

Exceptions:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)

Location Name: Rose Drive & Cambridge

Standards Met:

3, 5, 6a

Standards Not Met:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no shelter or pad. There is space 15 feet west to build.
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no shelter or pad. There is space 15 feet west to build.
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no shelter or pad. There is space 15 feet west to build.

Location Name: Military West & Southhampton

Standards Met:

1, 3, 5, 6a

Standards Not Met:

- 2 *Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
No bus shelter or pad only sidewalk
- 4 *Are all bus stop shelters/pads connected to the boarding area by an accessible*
No bus shelter or pad only sidewalk

Location Name: Southhampton & Hastings

Standards Met:

3, 5, 6a

Standards Not Met:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no shelter or pad. Room behind to construct.
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no shelter or pad. Room behind to construct.
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no shelter or pad. Room behind to construct.

Location Name: Benicia Middle School

Standards Met:

3, 5, 6a

Standards Not Met:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no shelter or pad. There is space 5 feet west to build.
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no shelter or pad. There is space 5 feet west to build.
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no shelter or pad. There is space 5 feet west to build.

Location Name: Solano & Larkin Dr

Standards Met:

3, 5, 6a

Exceptions:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)

Location Name: Raley's Shopping Center

Standards Met:

3, 5, 6a

Standards Not Met:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is a shelter but it is taken up complete by the bench inside. A person in a wheelchair could theatrically fit, but it would be tight
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
No pad just sidewalk
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
No pad just sidewalk

Location Name: Chelsea Hills & Warwick

Standards Met:

3, 5, 6a

Exceptions:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no Bus Stop shelter or pad. Southampton Swim Club Parking Lot limits adequate space --Exceptions Used (1, 3, 9, 10)
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no Bus Stop shelter or pad. Southampton Swim Club Parking Lot limits adequate space --Exceptions Used (1, 3, 9, 10)
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no Bus Stop shelter or pad. Southampton Swim Club Parking Lot limits adequate space --Exceptions Used (1, 3, 9, 10)

Location Name: Mary Farmer (Drolette Way)

Standards Met:

3, 5, 6a

Standards Not Met:

- 1 *Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no shelter or pad. Room behind to construct.
- 2 *Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no shelter or pad. Room behind to construct.
- 4 *Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no shelter or pad. Room behind to construct.

Location Name: Bencicia High (North and South)

Standards Met:

1, 3, 5

Standards Not Met:

- 2 *Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no bus stop pad only sidewalk.
- 4 *Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no bus stop pad only sidewalk.
- 6 *Are all bus route identification signs compliant with all sign requirements?*
There is no bus stop sign, appears to have been removed

Location Name: First Street & Military West

Standards Met:

3, 5, 6a

Standards Not Met:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no shelter or pad. Room behind to construct.
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no shelter or pad. Room behind to construct.
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no shelter or pad. Room behind to construct.

Location Name: East 4th between I & J

Standards Met:

3, 5, 6a

Exceptions:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used ()
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used ()
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used ()

Location Name: East 5th & O St (East & West)

Standards Met:

1, 3, 5, 6a

Standards Not Met:

- 2 *Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
No bus stop pad only sidewalk
- 4 *Are all bus stop shelters/pads connected to the boarding area by an accessible*
No bus stop pad only sidewalk

Location Name: Viewmont Stop

Standards Met:

6

Exceptions:

- 1 Is there clear wheelchair space min 30" w by 48" l inside all bus stop shelters*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)
- 2 Is there clear wheelchair space min 30" w by 48" long at all bus stop pads?*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)
- 3 Is the surface slope at all bus stops shelters, pads and egresses max 1:50 (2%)*
Surface slop of shelter is 12.4%. This is due to the slope of the hill --Exceptions Used (1, 3, 9, 10)
- 4 Are all bus stop shelters/pads connected to the boarding area by an accessible*
There is no Bus Stop shelter or pad. Private residences surround providing inadequate space
--Exceptions Used (1, 3, 9, 10)
- 5 Are all bus stop egresses connected to an accessible entrance by an accessible path*
The hill is too steep for connection to be an accessible path of travel --Exceptions Used (1, 3, 9, 10)

Location Name: Maria Field

Standards Met:

1, 2, 3, 4

Exceptions:

5 *Are all bus stop egresses connected to an accessible entrance by an accessible path*

While there is a connection, it requires significant extra travel going through and around the fields. Recommend paving a new alternate path from stop to Field. --Exceptions Used (1, 3, 9, 10)

Standards Not Met:

6 *Are all bus route identification signs compliant with all sign requirements?*

No bus stop sign at all. Appears to be stolen.