

Appendix D

PRA Group EVA Road Hiking Trail Photo exhibit to supplement Five-Year Report

In December of 2012 the PRA Group (PRAG) furnished a review of the EVA Road and Hiking Trail for the City of Benicia titled **EVA ROAD/HIKING TRAIL EROSION REVIEW**. In this review, PRAG identified 12 locations along the EVA Road/Hiking Trail with erosion and made recommendations to the City. Kennedy & Associates has added Appendix D – EVA Road Hiking Trail Follow Up to give the reviewer of this report an update as to the conditions at these locations 18-months later.

Our findings are consistent with our inspections since 2006. All of the areas identified in the PRAG Review have existed from 2008-2010. Monitoring of these areas will continue as instructed by City staff.

**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 1A



Photo 1B



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 2A



Photo 2B



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 3



Photo 4



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 5



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 6A



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtlot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 6B



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 7



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tortelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 8



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 9



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 10



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 11A



Photo 11B



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Photo 12



**Appendix D – EVA Road Hiking Trail PRAG Follow Up
Tortelot Five-Year Inspection Wrap-Up Report
June 2014**