

**Appendix A – Miscellaneous Wetlands Area Photos
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

Wetlands Area



**Appendix A – Miscellaneous Wetlands Area Photos
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**

New Outfall Trash Rack



Water levels are at the appropriate level



**Appendix A – Miscellaneous Wetlands Area Photos
Turtleot Five-Year Inspection Wrap-Up Report
June 2014**

Wetlands Signage



Appendix A – Miscellaneous Wetlands Area Photos
Turtleot Five-Year Inspection Wrap-Up Report
June 2014



**Appendix A – Miscellaneous Wetlands Area Photos
Turtleot Five-Year Inspection Wrap-Up Report
June 2014**



Wetlands signage could use cleaning

**Appendix A – Miscellaneous Wetlands Area Photos
Tortelot Five-Year Inspection Wrap-Up Report
June 2014**

Thorny Plant Restoration – Thorny Plants struggling to grow.



**Appendix A – Miscellaneous Wetlands Area Photos
Turtleot Five-Year Inspection Wrap-Up Report
June 2014**



None of the Thorny Plants in this section survived.

**Appendix A – Miscellaneous Wetlands Area Photos
Tourtlot Five-Year Inspection Wrap-Up Report
June 2014**



Another section where the Thorny Plants have not survived since being planted. The vegetation that has grown in does provide a very good barrier to keep people out of the Wetlands Area.

**Appendix A – Miscellaneous Wetlands Area Photos
Turtleot Five-Year Inspection Wrap-Up Report
June 2014**



There are a few Thorny Plants that have survived. They are still very small.



**Appendix A – Miscellaneous Wetlands Area Photos
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014**



More examples of planting areas where the Thorny Plants did not survive.



Appendix A – Miscellaneous Wetlands Area Photos
Tourtelot Five-Year Inspection Wrap-Up Report
June 2014



**Appendix A – Miscellaneous Wetlands Area Photos
Turtleot Five-Year Inspection Wrap-Up Report
June 2014**

Station's that are now within a wetlands area. (Stations 11, 12 and 13) Photo taken from Station 10.



**Appendix A – Miscellaneous Wetlands Area Photos
Tortelot Five-Year Inspection Wrap-Up Report
June 2014**



Looking westerly from the head wall, a lot of foliage has grown over this area where Thorny Plants were placed prior to last years inspection.