





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 2 of 117



instructor and inspector. The subject building is in extreme stress apparently due to a major soil failure beneath the structure. The collateral damage is exacerbated by multiple decades of deferred maintenance.



**4LEAF, INC.**


ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

# Inspector Field Report

City of Benicia  
SAP Evaluation of 670 East H street.  
Project#: Benicia 4LEAF#: ???  
CM: Chris Gale  
Inspector Chris Gale

IFR#: 001 DATE: 12/17/15  
Last Site Visit: NA

Page 3 of 117

Soil Subside of building	Soil & building and corrosive
	
Building has collapsed onto itself, the basement is gone.	Brick and mortar are falling from buildings on site at all locations.
Foundation/footing concrete is on site causing additional safety hazards	Brick and mortar have exceeded design life span and have degraded Back to base elements.



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???



CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 4 of 117

	
Buildings are splaying apart, adding eccentric loads and are not structurally sound.	Safety fencing has been repeatedly illegally bypassed by vandals.

Note; Even with proper protections installed these buildings are still be accessed and are so significantly damaged that they will continue to collapse. The materials used to construct these buildings are no longer able to sustain any significant loads. The materials cannot be reused as the required testing will show clearly.



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???



CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 5 of 117

Wall is failing, cracked, listing, leaning and rotted.	There is little to no structural connection to building at parapet.
	
Front and side wall failing at the 2 <sup>nd</sup> floor plate line.	No seismic retrofitting was observed in critical locations.



**4LEAF, INC.**


ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

# Inspector Field Report

City of Benicia  
SAP Evaluation of 670 East H street.  
Project#: Benicia                      4LEAF#: ???  
CM: Chris Gale  
Inspector Chris Gale

IFR#: 001    DATE: 12/17/15  
Last Site Visit: NA

Page 6 of 117



Both buildings are situated adjacent to high seismic hazards as well as soil prone to liquefaction.



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 7 of 117



MASONRY WALL

Structural cracks as well  
the mortar has  
y. Bricks have  
dust in multiple



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 8 of 117



N RODS

n rods for the  
has no  
sist any



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale


Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 9 of 117

Walls are wavering, not plumb or square any longer. Much of the brick is broken or cracked.





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 10 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 11 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 12 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 13 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 14 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 15 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 16 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 17 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 18 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 19 of 117



Rot of structural members and evidence of lead paint.



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 20 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 21 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 22 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

City of  
SAP Ev  
Project#  
CM: C  
Inspect



DATE: 12/17/15  
Site Visit: NA

Page 23 of 117



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 24 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 25 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 26 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 27 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 28 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 29 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 30 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 31 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 32 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 33 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 34 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 35 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 36 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 37 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 38 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 39 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 40 of 117

