



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 41 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 42 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 43 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 44 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 45 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 46 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 47 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 48 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 49 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 50 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 51 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 52 of 117



Collapses and mortar less brick work.



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 53 of 117



Collapsed brick wall with wood blocking strewn in.



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 54 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 55 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 56 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 57 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 58 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 59 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 60 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 61 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 62 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 63 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 64 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 65 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 66 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 67 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 68 of 117



Fire damage



**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 69 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 70 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 71 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 72 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 73 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 74 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 75 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 76 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 77 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???


CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 78 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 79 of 117





**4LEAF, INC.**

ENGINEERING • CONSTRUCTION MANAGEMENT  
BUILDING INSPECTION • PLAN CHECK

## Inspector Field Report

City of Benicia

SAP Evaluation of 670 East H street.

Project#: Benicia

4LEAF#: ???

CM: Chris Gale

Inspector Chris Gale

IFR#: 001 DATE: 12/17/15

Last Site Visit: NA

Page 80 of 117

