

| Record #   | Record Type           | Address                                   | Issued Date     | Complete Description of All Proposed Work:  |
|------------|-----------------------|---|-----------------|---|
| ENC-24-91  | Encroachment Permit   | 1034 First Street, Benicia, CA 94510      | August 1, 2024  | Extension of an existing patio to the edge of side walk.  |
| ENC-24-118 | Encroachment Permit   | 401 East I Street, Benicia, CA 94510      | August 1, 2024  | Temporary closure of sidewalk and parking lane for tree removal   |
| ENC-24-82  | Encroachment Permit   | 885 Wainwright Street, Benicia, CA 94510  | August 7, 2024  | Excavation at property line to replace approx. 6' of cast iron sewer lateral pipe and install new wye connection in city mainline.  |
| ENC-24-120 | Encroachment Permit   | 96 Carlisle Way, Benicia, CA 94510        | August 12, 2024 | AT&T to dig a pit in the sidewalk to expose and repair telephone cable. Restore and repair.   |
| ENC-24-121 | Encroachment Permit   | 921 East Fourth Street, Benicia, CA 94510 | August 12, 2024 | Dig 2'X6.5'deep (20.5 CU FT) hole to extract the existing 30' pole. Replace with new pole loc. (P.16) in the same hole.   |
| ENC-24-122 | Encroachment Permit   | 345 Industrial Way, Benicia, CA 94510     | August 13, 2024 | Tie in at existing pole and overlash 10 of new cable then continue on private property.   |
| ENC-24-109 | Encroachment Permit   | 150 East K Street, Benicia, CA 94510      | August 15, 2024 | PG&E to excavate to install (4) anodes, (2) ground rods & anode junction box for corrosion protection system of gas main. Permit to include all necessary restoration.  |
| ENC-24-119 | Encroachment Permit   | 2500 Lake Herman Road, Benicia, CA 94510  | August 16, 2024 | PG&E contractor to perform vegetation maintenance on and around PGE power lines and facilities. This tree work is a removal.  |
| ENC-24-130 | Encroachment Permit   | 430 Mills Drive, Benicia, CA 94510        | August 21, 2024 | COMCAST- Tie in at existing vault on and bore 96ft. Along street to existing vault. Install 2" conduit for service.   |
| ENC-24-124 | Encroachment Permit   | 479 McAllister Drive, Benicia, CA 94510   | August 28, 2024 | COMCAST- to replace existing pedestal with new pedestal.  |
| TR-24-62   | Transportation Permit | 849 Jackson Street, Benicia, CA 94510     | August 1, 2024  | Head Cover  |
| TR-24-63   | Transportation Permit | 401 West Channel Road, Benicia, CA 94510  | August 5, 2024  | ADU Building  |
| TR-24-65   | Transportation Permit | 401 West Channel Road, Benicia, CA 94510  | August 6, 2024  | 13-16 Drill with attachments  |
| TR-24-66   | Transportation Permit | 401 West Channel Road, Benicia, CA 94510  | August 8, 2024  | TM20 Drill rig with attachments   |
| TR-24-67   | Transportation Permit | 401 West Channel Road, Benicia, CA 94510  | August 14, 2024 | 637 Scraper   |
| TR-24-68   | Transportation Permit | 401 West Channel Road, Benicia, CA 94510  | August 14, 2024 | 637 Scraper   |
| TR-24-69   | Transportation Permit | 3195 Park Road, Unit C, Benicia, CA 94510 | August 28, 2024 | 90 Ton RT   |
| T-24-6     | Tree Removal          | 147 Von Pfister Alley, Benicia, CA 94510  | August 1, 2024  | The Palm tree is in the middle of the Von Pfister Alley. It has to be removed as this is a right-of-way, blocking an excavation needed for electrical work on a previously approved permit.   |
| T-24-7     | Tree Removal          | 1776 London Drive, Benicia, CA 94510      | August 1, 2024  | Two tall trees growing from one trunk at a severe angle from a sloping hillside. Both trees have lots of dead branches. Due to proximity to structures, tree presents significant safety issues especially during high winds or wet conditions. |
| T-24-10    | Tree Removal          | 54 La Cruz Avenue, Benicia, CA 94510      | August 23, 2024 | Remove an Italian stone pine from my backyard. Plus, I've had a few arborists state that it is structurally compromised.  |
| T-24-9     | Tree Removal          | 1618 Bayview Circle, Benicia, CA 94510    | August 27, 2024 | Rotted tree that is a hazard.   |
| T-24-12    | Tree Removal          | 1606 Bayview Circle, Benicia, CA 94510    | August 27, 2024 | Remove tree that has significant tree rot.  |
| T-24-13    | Tree Trimming         | 305 West K Street, Benicia, CA 94510      | August 13, 2024 | Tree trimming   |
| T-24-14    | Tree Trimming         | 1432 Drolette Way, Benicia, CA 94510      | August 20, 2024 | Tree trimming   |